

Material Safety Data Sheet For Armco Products

OO 782

Armco Inc.
General Offices
703 Curtis Street
Middletown, Ohio 45043

		J.,			
C	20	ŧi.	'nn	1	ı

PRODUCT NAME OR NUMBER	EMERGENCY TELEPHONE NUMBER
6AL-4V PWA-1215 Triple Melt to E-522F-12	513 / 425 - 5864
MANUFACTURING FACILITY, COMPANY R SUBSIDIARY	
OREGON METALLURGICAL CORPORATION	
530 W. 34th Ave., Albany, OR 97321	
DOT HAZARDOUS MATERIAL PROPER SHIPPING NAME 4910 FR 1730	DOT HAZARD CLASS (49 CFR 172.101)
N/A	N/A
Titanium Alloy N/A	DOT IDENTIFICATION NO. (4) CFR 172,101

JAN 1 1 1990 Section II CHEMICAL COMPONENTS			
ection II CHEMICAL COMPONENTS	- (1)	C.A.S. NUMBER	⁶⁴ 5
Titanium	<i>غ</i>	7440-32-6	9 0
Aluminum		7429-90-5	6
Vanadium		7440-62-2	4
			Property of a common property of the second
	lary xac		

Section	111	PHYSICAL DATA

Boiling Point	N/A	Solubility in Water	Insoluble	Evaporative Rate (Ethyl ether = 1)	N/A
Vapor Pressure mm Hg @ 20° C	N/A	Specific Gravity $(H_2O = 1)$	4.5	pH =	N/A
Vapor Density (Air = 1)	N/A	Percent Volatile by Volume	. 0		N/A
APPEARANCE AND ODOR	iorless	gray ingots and bi	llets		

_ !					
Section	1 I V	FIRE	Δ ND	EXPLOSION HAZARD DATA	

	LEL N/A % UEL N/A % IGNITION TEMPERATURE F N/A
EXTIN	Dry salt or powder extinguisher for metal fire, inert gas (Argon, Helium)
	Remove uninvolved material, allow fire to burn out. Cover involved material with
	salt or powder from extinguisher. If fire in container, smother with inert gas,
UNUS	Do not use water or other liquid extinguishers as hydrogen may be evolved.
State Land	Nitrogen and carbon dioxide are ineffective.

en e con en compete en energia de la compete de la comp	effects would	d be expected under normal usage. The "nuisance	
dust" star	ndard would a	The control of the co	And the second s
A			
		· · · · · · · · · · · · · · · · · · ·	
		the first transfer of	
		and the second s	Special Specia
the districts left frameworks are constructed and promote transposed to the paper of the con-	. Mallaco - contrago - con any contra respect por por por a paragraphic and contragance and		State of Subjections of the control
nilyaniantenpartentation in terretoring you programme in a section of	e integral of graph for processes assert tendension of make it is a con-		Neg Militarios para mangar manasinsas .
		<u> </u>	
and expension, deleterate designs are years unless surrections and the second			
ction VI RE	EACTIVITY DA	ATA	
CHOIL AT	CONDITIONS TO	AVOID	
TABLE UNSTABLE	E	Open flames, excessive heat	
COMPATIBILITY (M	ATERIALS TO AVO	Strong oxidizing or reducing agents	
ECOMPOSITION PRO	DUCTS Tita	unium dioxide, aluminum oxide, vanadium pentoxide	
HAZARDOUS MA	Y OCCUR	CONDITIONS TO AVOID N/A	
POLYMER-			
1 111	L NOT OCCUR X		
ction VII SP	HILORIFAK	PROCEDURES	
TEPS TO BE TAKE	EN IN CASE MATE	ERIAL IS RELEASED OR SPILLED	
Recover ma	terial if po	ssible	
			·
Landfill 1	п accordance	with applicable local, state and federal regula	tions
·			
			7.7
tion VII PE	RSONNEL PRO	OTECTION INFORMATION	
No coostal	precautions		
No speciar			and the second s
No special			
no special	and the company of th		
No special	in the control of the		7 - 2 3 3002 1002
NO SPECIAL			
etion IX SP		UTIONS AND ADDITIONAL INFORMATION	
ction IX SP		MUTIONS AND ADDITIONAL INFORMATION material - hard to ignite, but very difficult to	
etion IX SP	combustible)

While the information and recommendations set forth on this data sheet are believed to be accurate as of the present date, ARMCO MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.

Prepared by: STEPHEN S. I

STEPHEN S. FELTON
Corporate Toxic Substances Engineer

Steplen 1. Foltom